



GANSEVOORT TRIANGLE

9-19 9TH AVE, NEW YORK, NY, 10014



HIGGINS QUASEBARTH & PARTNERS, LLC  
CONSULTANTS IN PRESERVATION AND REHABILITATION OF HISTORIC PROPERTIES

BKSK

CB2 PRESENTATION - 04.28.2014



# URBAN SQUARE SITE ANALYSIS - APPROACH


9-19 9TH AVE, NEW YORK, NY, 10014




HIGGINS QUASEBARTH & PARTNERS, LLC  
CONSULTANTS IN PRESERVATION AND REHABILITATION OF HISTORIC PROPERTIES

BKSK

CB2 PRESENTATION - 04.28.2014



HORIZONTAL BANDS/PROPORTION



DELINEATION



"FLOATING MASONRY"

## PROPORTIONS

9-19 9TH AVE, NEW YORK, NY, 10014



HIGGINS QUASEBARTH & PARTNERS, LLC  
CONSULTANTS IN PRESERVATION AND REHABILITATION OF HISTORIC PROPERTIES

BKSK


CB2 PRESENTATION - 04.28.2014



DETAIL RENDERING



INITIAL CONCEPT



# MATERIALS / PATTERN

9-19 9TH AVE, NEW YORK, NY, 10014



HIGGINS QUASEBARTH & PARTNERS, LLC  
CONSULTANTS IN PRESERVATION AND REHABILITATION OF HISTORIC PROPERTIES

# BKSK

CB2 PRESENTATION - 04.28.2014



9-19 9TH AVE, NEW YORK, NY, 10014



HIGGINS QUASEBARTH & PARTNERS, LLC  
CONSULTANTS IN PRESERVATION AND REHABILITATION OF HISTORIC PROPERTIES

BKSK

CB2 PRESENTATION - 04.28.2014