


Ρ Κ S Β

Greenwich Village Historic District and Historic Map

41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019



Ρ Κ S Β

41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019

Site Survey

LPC

2



1940 Tax Photo

Κ

B

Ρ

S



1980 Tax Photo

No. 41, alone of the entire row, still displays low attic windows and modillions at the roof cornice. It may be considered late Greek Revival in style. Now a five-story house, it has been remodeled to provide a basement entrance with restaurant. Originally it was four stories high with basement, as may be seen from the high stone lintel of the doorway which remains embedded in the masonry, when a small window took the place of the door at the left side. The house was built in 1848-49 by Foster & Van Ostrand. In the early Eighteen-fifties, this was the home of R. W. Jeffery.

GREENWICH AVENUE West Side (Betw. Perry & Charles Sts.)


Tax Photos and Designation

LPC 3



Ρ

S





Existing Site Plan

LPC

4



Ρ

S


Κ

Β



Proposed Site Plan

LPC 5



Ρ

S

+

Κ

Β

August 13, 2019

Existing Section


LPC

6

41 Greenwich Avenue Landmarks Preservation Commission



RESIDENTIAL



Ρ

S

Κ

Β

41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019

Proposed Section

LPC

7



RESIDENTIAL



Ρ

S


+


Κ

Β

Greenwich Avenue Rear Elevation - Existing

41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019





Rear Wall - Existing Condition

LPC 9



Ρ

S

+

Κ

Β

Greenwich Avenue Rear Elevation - Proposed

41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019





- ADJACENT 5 STORY




Landmarks Preservation Commission August 13, 2019

11


Κ

Β

S







GREENWICH AVENUE



Existing and Proposed Second Floor Plan


41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019

Κ


Β

S









GREENWICH AVENUE




Existing and Proposed Third Floor Plan

41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019


Κ

Β

S



72'-4 3/4" BASED ON L&B SURVEY



GREENWICH AVENUE



Existing and Proposed Fourth Floor Plan


LPC 14


Κ


Β

S









GREENWICH AVENUE

Existing and Proposed Roof Plan

LPC

15

PCS Engineering, PLLC

93 Madison Ave. Valhalla, NY 10595 Tel:(914) 629-5578 Fax: (914)-761-2214 pcsengineering@gmail.com

February 15, 2016

Ms. Valerie Coster 41 Greenwich Ave LLC 443 Lexington Ave New York, NY 10001

Re: Inspection and Structural Assessment 41 Greenwich Ave., Manhattan, NY

Per your request we performed an inspection of the property at 41 Greenwich Avenue, Manhattan, NY, on January 26, 2016. Our observations, assessment of the structural conditions observed and our recommendations for rehabilitation of the building structural elements are provided below.

The subject property is a four story mixed use building in a mixed use destruct of Manhattan, NY. The building was constructed circa 1848. The building is constructed with common brick walls and wood floor joists. The building is approximately 21 feet wide. The floor joists span from side wall to side wall and are supported by pockets in the brick masonry.

The upper floors contain several residences. The floors are supported on 3"x 10" wood floor joists, likely original construction. Several of the floors suffer from significant deviation from level resulting from the deterioration of the long term floor joists. The floor drop in some cases exceeds 3 inches over the width of the room which creates an unsafe condition. Over time the wood joists have developed permanent deflection from aging of the wood and the sustained loads. The joists are no longer serviceable and need to be replaced. The attached photos show details where reinforcement has been applied and where shimming is required to maintain a level finished ceiling due to the excessive slope of the joists.

We would recommend the demolition of the floor structural systems and the joist replaced with suitably sized modern laminated joists. These engineered structural members have allowable stress levels far exceeding typical structural lumber and therefore will not experience the long term permanent deflect deterioration as did the original floor joist timbers.

We also examined the front and rear facades of the building. 41 Greenwich Ave is an independent structure that has a varying overall height from the buildings on either side. The

ENGINEER'S REPORT 02-16-2016

Β

front façade appears in basically good condition requiring a detailed inspection, some repointing and possible localized brick replacement. The cornice appears to have deterioration issues typical of cornices of this vintage. Likely the wood sub-members have deteriorated and lost their ability to hold fasteners. In our opinion the most prudent approach is to replicate and replace the existing cornice with a fiberglass cornice assembly.

The rear facade has deterioration issues. A white coating applied to the brick sometime in the past has trapped moisture in the brick, which after repeated freeze-thaw cycles had deteriorated the structural capacity of the brick. We would recommend demolition and replacement of the rear façade wall.

The rear wall can be rebuilt with common brick and masonry lintels to match the original construction and architectural details. The new brick materials should be either uncoated or coated with a breathable style material to allow moisture to escape the brick substrate. This will maximize the service life of the new rear wall.

	If you h	nave any	questions	or require	some	furth
mail or	call					



LPC

16

her information, please do not hesitate to e-

Sincerely yours. Michael P. Walsh, P.E. PCS Engineering, PLLC



41 Greenwich-8 Rear facade



ENGINEER'S REPORT 02-16-2016 Ρ

Κ

Β

S

41 Greenwich-9 Rear facade

41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019



41 Greenwich-10 Rear facade



41 Greenwich-11 Rear facade




41 Greenwich-12 Rear facade


ENGINEER'S REPORT 02-16-2016


S


Β


41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019


















TOTAL	5,932 GSF	-211 GSF	-1,230 SF	1,352 ZSF	3,139 ZSF	4,491 ZSF
FAR (ZFA / 1,570 SF)				0.86	2.0	2.86
PERMITTED FAR				2.0	2.01	2.01









LOT 64 PROPOSED CONDITION 1,570 SF

	-	
RALL	FLOOR	AREA

IAL	ZONING FLOOR AREA
	0
	1,567
	137
	929
	929
	929
	0

______^{ms} Architec s^{+,K} 11-2-16 APPRUD 330 W42 STREET NEW YORK NY 10036 T 212 594 2010 F 212 947 4381 Mechanical Engin

Kohler Ronan, LLC

171 Madison Avenue New York, NY 10016 T (212) 695-2422 F (212) 695-2423 Structural Enginee

SILMAN

32 Old Silp, 10th Floor New York, NY 10005 T (212) 620-7970 F (212) 620-8167

Location Plan



DOB BSCAN

DOB STAM

1 - ISSUE FOR FILING	04/06/2016 Date
Project	
41 Greenw	ich Ave
Drawing Title	
ZONING DIAGR	AMS
FAR CALCS	


COMMERCIA (EXISTING)


COMMERCIAL (NEW)




LOT LINE


- - REQ'D SETBACK









 \bigcirc 1 second floor demolition plan $_{1/4^{\ast}~=~1^{\prime}-0^{\ast}}$



 $02 \, {}^{\text{THIRD}}_{\text{1/4"}} \, {}^{\text{FLOOR}}_{\text{Demolition}} \, {}^{\text{PLON}}_{\text{PLAN}}$





Kohler Ronan, LLC

171 Madison Avenue New York, NY 10016 T (212) 695-2422 F (212) 695-2423

Structural Engineer

Mechanical Engi

SILMAN


32 Old Slip, 10th Floor New York, NY 10005 T (212) 620-7670 F (212) 620-8157

Location Plan



DOB BSCAN


DOB STAMP




41 Greenwich Ave.



 $O 1_{1/4^{*} = 1^{\prime}-0^{*}}^{\text{FOURTH} FLOOR DEMOLITION PLAN}$







GREENWICH AVENUE

ms Archite 11-2-11 Р_К S В APPRUD 330 W42 STREET NEW YORK NY 10036 T 212 594 2010 F 212 947 4381 Kohler Ronan, LLC 171 Madison Avenue New York, NY 10016 T (212) 695-2422 F (212) 695-2423 Structural Enginee SILMAN 32 Old Slip, 10th Floor New York, NY 10005 T (212) 620-7970 F (212) 620-6157 Location Plan • HARLES STREET


DOB BSCAN

DOB STAMP


1 - ISSUE FOR FILING	04/06/2016
Issue	Date
Project	
11 Croone	ich Auc
41 Greenw	ich Av



 $O 1 \underset{1/4"}{\text{SECOND}}{\text{FLOOR}} CONSTRUCTION PLAN$



 $02 \, {}^{\rm THIRD}_{\rm 1/4"\,=\,1'-0"}$ floor construction plan






NUE	PERRY ST	TREET	
11	IIE	D)	GRE
-4-	HĘ		GREENWICH AVENUE
	1 t		HAVEN
CHARIES		•	S.
	STREET	RI) ck#612
	CHARLES	PERRY S	CHARLES STREET

DOB BSCAN

DOB STAMP

1 - ISSUE FOR FILING	04/06/2016
Issue Project	Date
41 Greenw	ich Ave
Drawing	
Title	
	HIRD
Title	





_____ms Archit **K** 2:16 P + SBPRUD 330 W42 STREET NEW YORK NY 10036 T 212 564 2010 F 212 547 4381 Mechanical Er Kohler Ronan, LLC 171 Madison Avenue New York, NY 10016 T (212) 695-2422 F (212) 695-242 Structural Engineer

SILMAN

32 Old Slip, 10th Floor New York, NY 10005 T (212) 620-7970 F (212) 620-8157


Location Plan



DOB BSCAN


DOB STAMP


TER ROOFTOP_ACCESS_LANDINGS_REQUIRED; FC504.4.1.1: MINIMUM_CLEARANCE OF 6' X 6' X 9'H FOR EVERY 12 FEET OF BUILDING PERMIETER ES GREENWICH AVENUE: 21.00'/12 = 10 CLEARANCE 2_LANDINGS_REQUIRED,



41 Greenwich Ave.











Ρ K +S Β

Rear Wall - Built Condition


LPC 26




41 GREENWICH AVENUE

View from Terrace - Looking Northwest to Adjacent Yards


41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019





Views of Terrace

LPC 28



Proposed Site Plan with Built Condition

41 Greenwich Avenue Landmarks Preservation Commission August 13, 2019