



TAX PHOTO CIRCA 1941



LANDMARK DESIGNATION PHOTO 1980' 5



LATEST PHOTO 2016




INDICATES EXISTING ENTRANCE DOOR @ I I 6 W. HOUSTON STREET LOOKING NORTH



INDICATES EXISTING ENTRANCE DOOR @ 116 W. HOUSTON STREET LOOKING SW



PHOTO INDICATES EXISTING ENTRANCE DOOR @ PROPOSED ENTRANCE DOOR @ 116 W. HOUSTON STREET



116 W. HOUSTON STREET

SCALE: 3/8" = 1'-0"

ENTRY LOBBY DOOR REPLACEMENT 116 W HOUSTON ST. NEW YORK NY

EXISTING FACADE PHOTOS & PROPOSED ELEVATION

A-102.00