



19-21 Grove Street

Facade Restoration Work

Located Within the Greenwich Village Historic District



EXISTING PHOTO




HISTORIC ENTRANCE DOOR FLAT ARCH




HISTORIC PHOTO




HISTORIC PHOTO




EXISTING ELEVATION




PROPOSED ELEVATION




PROPOSED ELEVATION




DOOR SURROUND



GHOSTED STUCCO WINDOW
PROPOSED SECTION




TYPICAL WALL



EXISTING SECTION



EXISTING FACADE



PROPOSED FACADE